Work Order ID 58591

Page 1

Item ID:

D4035-041

Wednesday, May 12, 2010 8:43:52 AM

Accept

Setup Start

Stop



**Revision ID:** 

Item Name:

Lid Rib Assembly, Fwd (350 Basket)

**Start Date:** 

5/12/2010

Start Qty: 2.00

Reg'd Oty: 2.00



**Cust Item ID:** 

**Customer:** 

Reference:

Approvals:

Required Date: 5/14/2010

Process Plan: M

Date:

Date: 10-5-19 Tooling:

Date:

Start Run



SPC (Y/N):

Date:

Stop

Sequence ID/ Work Center ID Operation

**Revision Nbr** 

Α

Set Up/

Draw

Plan Draw Code Reject **Qty** 

Reject

Insp.

**Draw Nbr** 

Description

**Run Hours** 

Number

Rev.

Accept Qty

5 St 10/05/13

Number Stamp

D4035 100

Large Fab Large Fab

Memo

0.00

0.00

1- Cut D4035-1 as per dwg D4035

Weld per dwg A/R S.S. rod Batch: 41/3328

2- Drill as per dwg D4035 using DT9562 3- remove identification marks and deburr

10.65-13

4- Weld bushing in rib as per dwg D4035

110

Quality Control

QC9- Inspect visual per QSI004- Fusion Welds

0.00

Memo

0.00

D 10.05, 18

D	art	Aer	osp	ace	Ltd

W/O:			W	ORK ORDER CHAN	GES					
DATE	STEP	PROCEDURE CHANGE				Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
	, 			•						
Part No:	·	PAR #:	Fault Cat	egory:	NCI	R: Yes	No DQA	\:	Date:	
				Disposition: QA					•	
NCR:		V	VORK ORE	DER NON-CONFORM	IANCE	(NCR	)			
DATE	STEP	Description of NC			ction B	Verificat		ation	Approval	Approval
		Section A	Initial Chief Eng	Action Description Chief Eng	1	Sign & Date	Section	n C	Chief Eng	QC Inspector
		·								
							<b></b>			
					: !					

## Work Order ID 58591

Wednesday, May 12, 2010 8:43:52 AM



Page 2

Item ID:

D4035-041

Accept

Setup Start

Stop



**Revision ID:** Item Name:

Lid Rib Assembly, Fwd (350 Basket)

**Start Date:** 

5/12/2010

Start Qty: 2.00

Req'd Qty: 2.00

**Cust Item ID:** 

**Customer:** 

Reference: Approvals:

Process Plan:

Date:

Tooling:

0.00

Date:

Run Start



Required Date: 5/14/2010

QC:

Date: \_\_\_\_\_ SPC (Y/N):

Date:

Stop



Sequence ID/ Work Center ID

120

Quality Control

Operation Description

QC5- Inspect part completeness to step on W/O

Set Up/ **Run Hours**  **Draw** Number

Draw Rev.

Plan Accept Code Qty

Reject Qty

Reject

Insp. Number Stamp

Memo

2 10/05/18

130

Packaging Packaging

Identify as per dwg & Stock Location:

0.00

0.00

PD 10.05.18

140

Quality Control

QC21- Final Inspection - Work Order Release

0.00

Memo

Memo

0.00

10/05/1898) PS-0-5-18

<b>Dart Aerospace L</b>	.td
-------------------------	-----

W/O:		WORK ORDER CHANGES					1		
DATE	STEP	PROCEDURE CHANGE			Ву	Date C	y	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No:		PAR #:						_ Date: _	
	R	esolution:	Disposition	:	_ QA: N/C C	osed:	<u> </u>	Date:	
NCR:			WORK ORDE	R NON-CONFORMA	NCE (NCF	R)			
DATE	STEP	Description of NC Section A	Initial Chief Eng	Corrective Action Section Action Description Chief Eng	on B Sign & Date			Approval Chief Eng	Approval QC Inspector
									-
								r Mari	
	. 4 <sup>11,2</sup>	· .							
		•							



IPP RevA: new issue DD 09.11.25 verified by:EC per dwg revA 10.03.15 verified by:EC

IPP Rev:B as

**Start Date: 5/12/2010** 

Required Date: 5/14/2010

Required Qty: 2.00

Component	Item	ID/
Item Name		
D2327-3		

Replacement	Mfg/
Item ID	Purch
•	Manuf

	Bin	Primary
•	Item	Location
ictured	No	

No

Last	
Location	

Route	Unit of
Seq ID	Measu
100	Each

Qty o re Hand 12.0000

n	Qty	per	Kit	

Start Qty: 2.00

Date Issued Issued Status

Page 1



Spacer Bushing

Location	Loc Qty	Loc Code
WA	12	
57790	12	

M304TS0.750W.049 Purchased

304 SQ Tube .75x.75x.049W

uc
193
19





<b>Location</b>	Loc Oty	Loc Code
MAT	200	
113763	0	
114323	200	
MAT017	143.9493368	
113763	24.25	
114298	119.699337	

Qty


Dart Aerospac	e Ltd
---------------	-------

W/O:		WORK ORDER CHANGES								
DATE	STEP	PRO	PROCEDURE CHANGE By Date						Approval Chief Eng / Prod Mgr	Approval QC Inspector
								1		
									`	
Part No		PAR #:							Date:	
	R	esolution:	Dispositi	on:	QA: N/C C	losed:	Date:			
NCR:		<b>\</b>	NORK ORI	DER NON-CONFORM	ANCE (NCF	₹)				
DATE	STEP	Description of NC Section A	Initial	Action Description	tion B			n	Approval Chief Eng	Approval QC Inspector
			Chief Eng	Chief Eng	Date					
<u></u>										
										:
NOTE: D	1									•







D4035-041 BASKET LID RIB ASSY, FWD



D4035-043 BASKET LID RIB ASSY, AFT



D4035-045 BASKET LID RIB ASSY, FWD (LIGHT)




D4035-047 BASKET LID RIB ASSY, AFT (LIGHT)




A	NEW IS	NEW ISSUE JPH							
REV.			DESCRIPTION	BY	DATE				
DESIG	4	AJS	DART AEROSPACE LTD						
DRAWN JPH			HAWKESBURY, ONTARIO, CANADA						
CHECKED			DRAWING NO.		REV. A				
MFG. APPR.		Z.	□ D4035		SHEET 1 OF 5				
APPROVED AND			TITLE		SCALE				
DE APPR.			BASKET LID RIB ASS	SY	NTS				
DATE	10.0	3.04	СОРУКІВНТ © 2010 BY DART  ТНЯ ООСІМЕНТ В МИКАТЕ АНО СОМОВНТЫ, АНО ІЗ ВИРРІ В  НОТ ТО ВЕ ИЗЕВ ГОТ МУ РИЗРОЗЕ ОК СОРЕВ ОЯ СОМИМЯ  ЖЕТТЕМ РЕЖИВООК РОМО DART AL	DON THE EXPRES	S CONDITION THAT IT IS				

## **Dart Aerospace Ltd** W/O: **WORK ORDER CHANGES Approval** DATE **Approval** STEP **PROCEDURE CHANGE** By Qly Date Chief Eng / QC Inspector Prod Mar Part No: \_\_\_\_\_\_ PAR #: \_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_ Date: \_\_\_\_\_ Resolution: \_\_\_\_\_ Disposition: \_\_\_\_ QA: N/C Closed: \_\_\_\_ Date: \_\_\_\_\_ **WORK ORDER NON-CONFORMANCE (NCR)** NCR: **Corrective Action** Section B **Description of NC** Verification DATE **STEP Approval** Approval Sign & Initial **Action Description** Section A QC Inspector Section C Chief Eng Chief Eng Chief Eng Date



Dart Ae	rospace	• Ltd								
W/O:			WC	ORK ORDER CHANGES	3		1			
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date	Qy	Approval Chief Eng / Prod Mgr	Approva QC Inspecto	
Part No		PAR #:	Fault Cate					Date: _		
	R	esolution:	Disposition	n:	QA: N/C CI	osed:		Date: _		
NCR:			WORK ORDI	ER NON-CONFORMAN	CE (NCF	R) .				
DATE	OTED	Description of NC	Corrective Action Section B			Verifica		Ammuoval	Approva	
DATE	TE STEP	E SIEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section		Approval Chief Eng	QC Inspect
							-			
							İ			



## **Dart Aerospace Ltd**

W/O:	WORK ORDER CHANGES										
DATE	STEP	PRO	PROCEDURE CHANGE By Date						y	Approval Chief Eng / Prod Mgr	Approval QC Inspector
							~,			·	
	- K										
Part No		PAR #:								Date:	-
-	R	esolution:	Disposition	·	_ QA:	N/C CI	osed:			Date:	
NCR:		<b>\</b>	WORK ORDE	R NON-CONFORMA	ANCE	(NCF	₹)				
DATE	STEP	Description of NC	Corrective Action Section B		ion B	Verifica		ati	tion	Approval	Approval
DAIL		Section A	Initial Chief Eng	Action Description Chief Eng		Sign 8 Date	Section			Chief Eng	QC Inspector
		•								·	
						95°.				-	
							¥				
NOTE: Da	ate & initi	al all entries						_			

H:\fFORMS\Quality Assurance\approved QA\NCRWO RevE